


Normstahl

INSTALLATION MANUAL NORMSTAHL OVERHEAD SECTIONAL DOOR OSP82 VL (VLA) TRACK


1




2




3




4




5




6




7




8




9




10




11

		
	 	$T = 2 = 7.5 \text{ MM} *$ $T > 2 = 8.5 \text{ MM}$
		10 MM
		10 MM
		5 MM
$*T < 2 \text{ MM} \times$		



12





13



14





15




16




T1 = 2 mm	T2 = 2 mm	T3 = 2 mm	T4 = 2 mm
T5 = 2 mm	T6 = 2 mm	T7 = 2 mm	T8 = 2 mm
T9 = 2 mm	T10 = 2 mm	T11 = 2 mm	T12 = 2 mm
T13 = 2 mm	T14 = 2 mm	T15 = 2 mm	T16 = 2 mm
T17 = 2 mm	T18 = 2 mm	T19 = 2 mm	T20 = 2 mm
T21 = 2 mm	T22 = 2 mm	T23 = 2 mm	T24 = 2 mm
T25 = 2 mm	T26 = 2 mm	T27 = 2 mm	T28 = 2 mm
T29 = 2 mm	T30 = 2 mm	T31 = 2 mm	T32 = 2 mm
T33 = 2 mm	T34 = 2 mm	T35 = 2 mm	T36 = 2 mm
T37 = 2 mm	T38 = 2 mm	T39 = 2 mm	T40 = 2 mm
T41 = 2 mm	T42 = 2 mm	T43 = 2 mm	T44 = 2 mm
T45 = 2 mm	T46 = 2 mm	T47 = 2 mm	T48 = 2 mm
T49 = 2 mm	T50 = 2 mm	T51 = 2 mm	T52 = 2 mm
T53 = 2 mm	T54 = 2 mm	T55 = 2 mm	T56 = 2 mm
T57 = 2 mm	T58 = 2 mm	T59 = 2 mm	T60 = 2 mm
T61 = 2 mm	T62 = 2 mm	T63 = 2 mm	T64 = 2 mm
T65 = 2 mm	T66 = 2 mm	T67 = 2 mm	T68 = 2 mm
T69 = 2 mm	T70 = 2 mm	T71 = 2 mm	T72 = 2 mm
T73 = 2 mm	T74 = 2 mm	T75 = 2 mm	T76 = 2 mm
T77 = 2 mm	T78 = 2 mm	T79 = 2 mm	T80 = 2 mm
T81 = 2 mm	T82 = 2 mm	T83 = 2 mm	T84 = 2 mm
T85 = 2 mm	T86 = 2 mm	T87 = 2 mm	T88 = 2 mm
T89 = 2 mm	T90 = 2 mm	T91 = 2 mm	T92 = 2 mm
T93 = 2 mm	T94 = 2 mm	T95 = 2 mm	T96 = 2 mm
T97 = 2 mm	T98 = 2 mm	T99 = 2 mm	T100 = 2 mm




17




18




19




20




21




22




23




24



25



26




OPTION


6,3x10mm

2x


29




30




31




32




33




34




35




36




37




38




39




40




41




42




43




44




45





46




47




48




49




50




51




52




53




54




55




56




57




58




59




60




61




62




63




64




65




66




67




68




69




70




71




72




73



74



75





Normstahl

www.normstahl.com