


Normstahl

INSTALLATION MANUAL NORMSTAHL INDUSTRIAL DOORS HHL (SHC) TRACK NON-PTS



K068400/H


1




2




3




4




5




6



7




8




9

OPTION




10


OPTION




11




12




13




14




15

			
			$T = 2 = 7.5 \text{ MM} *$ $T > 2 = 8.5 \text{ MM}$
			10 MM
			10 MM
			5 MM
$*T < 2 \text{ MM} \times$			


16




17




18




19




20




21




22




23




24




25




26




27



28




29




30


OPTION




31




32




33




34




35




36




37




38





39




40




41




43




44




45




46




47




48



49




50




OPTION DLW > 3000

51




52




53



OPTION
DLW > 3000



54




55




TORQUE SEQUENCE

- 1; A = 20 Nm
- 2; B = 20 Nm
- 3; C = 20 Nm
- 4; D = 20 Nm
- 5; A = 35 Nm (MAX.)
- 6; B = 35 Nm (MAX.)
- 7; C = 35 Nm (MAX.)
- 8; D = 35 Nm (MAX.)


56




57




58




59




60




61




62




63



64





65




66



OPTION




67




68




69




70




71




72




73




74




75




76




77




78




79




80




81




82




83




84




85




86




87




88




89




90



91



92





Normstahl

www.normstahl.com